

QUOTATION



AQUIFER MAINTENANCE & PERFORMANCE SYSTEMS, INC.

7146 Haverhill Road N. • West Palm Beach, FL 33407 • 561-494-2844

August 5, 2019

Pembroke Pines
Pembroke Pines, FL 33444
Attn: Karl Kennedy

Re: Well #9

AMPS, Inc. appreciates the opportunity to submit the following proposal for repairs needed to the pump & equipment pulled from well #9 for your review:

1) Disassemble pump & inspect all components, remove existing impeller; inspect Column & shafting performing runouts on the shafting 7 hours	\$ 630.00
2) Epoxy coat suction bowl, machine & replace wear ring	1,345.00
3) 1 - 12" Galvanized cone strainer	565.00
4) 1 - Collet for Flowservice model 16ENL	39.80
5) 1 - 12"x10"x1" Epoxy coated column pipe with shafting & spiders	3,575.95
6) 1 - Freight charges	392.05

TOTAL: \$ 12,373.85

If you have any questions or comments about the above information please feel free to give us a call. Thank you.

Sincerely,
Jayne L. Prindible
Comptroller

**FOR YOUR TOTAL PUMP & WELL FIELD NEEDS
ABOVE QUOTATION GOOD FOR 30 DAYS.**