Vehicles Sent or Marked for Surplus					
Vehicle #	Department	Description	Status		
7709	Fire Department	2008 Chevrolet Impala	Vehicle is 17 years old and being recommended for replacement		
7711	Fire Department	2008 Chevrolet Impala	Vehicle is 17 years old and being recommended for replacement		
4500	Fire Department	2002 FORD E350 VAN	Vehicle is 17 years old and being recommended for replacement		

City of

Pembroke Pines Fleet Services Vehicle Replacement Analysis and Summary

Vehicle #: Division/Unit: Year: Make/Model: Mileage:	7709 Fire 2008 Chevrolet Impala 129,976	
FACTOR	VALUE	DESCRIPTION
Age	17	Age of vehicle.
Miles	129,976	Number of miles.
Type of Service	Light-Duty	Type of service that vehicle receives. For instance, a police patrol car would be given "Severe" because it is in severe duty service. In contrast, an administrative sedan would be given "Admin," while light duty trucks will be given "Light-Duty."
Condition	Fair	Takes into consideration body condition, rust, interior condition, history, anticipated repairs, etc. Categories include, New, Very Good, Good, Fair, and Poor.

SUMMARY*

Fleet Manager's
Recommendation:Due to the age of the vehicle and operating conditions,
this asset is prone to several failures. One of these
failures comes in the form of an engine system failure.
At 17 years old this asset needs an engine overhaul,
fuel system overhaul, and cooling system repairs. The
body of the box and floor is a safety hazard to end user.
The parts, labor, and maintenance to keep this asset in
circulation is more than that of the depreciated value.
To sum up everything that has been stated, this unit
qualifies for replacement.

City of

Pembroke Pines Fleet Services Vehicle Replacement Analysis and Summary

Vehicle #: Division/Unit: Year: Make/Model: Mileage:	7711 Fire 2008 Chevrolet Impala 123,092	
FACTOR	VALUE	DESCRIPTION
Age	17	Age of vehicle.
Miles	123,092	Number of miles.
Type of Service	Light-Duty	Type of service that vehicle receives. For instance, a police patrol car would be given "Severe" because it is in severe duty service. In contrast, an administrative sedan would be given "Admin," while light duty trucks will be given "Light-Duty."
Condition	Fair	Takes into consideration body condition, rust, interior condition, history, anticipated repairs, etc. Categories include, New, Very Good, Good, Fair, and Poor.

SUMMARY*

Fleet Manager's
Recommendation:Due to the age of the vehicle and operating conditions,
this asset is prone to several failures. One of these
failures comes in the form of an engine system failure.
At 17 years old this asset needs an engine overhaul,
fuel system overhaul, and cooling system repairs. The
body of the box and floor is a safety hazard to end user.
The parts, labor, and maintenance to keep this asset in
circulation is more than that of the depreciated value.
To sum up everything that has been stated, this unit
qualifies for replacement.

City of

Pembroke Pines Fleet Services Vehicle Replacement Analysis and Summary

Vehicle #: Division/Unit: Year: Make/Model: Mileage:	4500 Fire 2002 Ford Box Truck 114,500	
FACTOR	VALUE	DESCRIPTION
Age	22	Age of vehicle.
Miles	114,500	Number of miles.
Type of Service	Light-Duty	Type of service that vehicle receives. For instance, a police patrol car would be given "Severe" because it is in severe duty service. In contrast, an administrative sedan would be given "Admin," while light duty trucks will be given "Light-Duty."
Condition	Fair	Takes into consideration body condition, rust, interior condition, history, anticipated repairs, etc. Categories include, New, Very Good, Good, Fair, and Poor.

SUMMARY*

Fleet Manager's
Recommendation:Due to the age of the vehicle and operating conditions,
this asset is prone to several failures. One of these
failures comes in the form of an engine system failure.
At 22 years old this asset needs an engine overhaul,
fuel system overhaul, and cooling system repairs. The
body of the box and floor is a safety hazard to end user.
The parts, labor, and maintenance to keep this asset in
circulation is more than that of the depreciated value.
To sum up everything that has been stated, this unit
qualifies for replacement.