| Vehicles Sent or markedfor Surplus | | | | | | |
|------------------------------------|---------------------|-----------------------|------------------|--|--|--|
| Vehicle # | Department | Description | Status | | | |
| | | | Meet replacement | | | |
| 7702 | Fire Department | 2007 Chevrolet Impala | criteria | | | |
| | | | Meet replacement | | | |
| 7703 | Fire Department | 2008 Chevrolet Impala | criteria | | | |
| | Technology Services | | Meet replacement | | | |
| 2235 | Department | 2016 GMC Terrain | criteria | | | |
| | | | | | | |
| | | | | | | |

| | Vehicles Sent or Marked for Surplus | | | | | |
|-----------|-------------------------------------|-------------------|--|---|--|--|
| Vehicle # | Department | Description | Status | | | |
| 7702 | FIRE DEPARTMENT | 2007 CHEVY IMPALA | 17 YEARS OLD VEHICLE USED, AND DAMAGE. | | | |
| 7703 | FIRE DEPARTMENT | 2007 CHEVY IMPALA | 17 YEARS OLD VEHICLE USED, AND DAMAGE. | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | - | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | ı | | | | | |

City of Pembroke Pines Fleet Services Vehicle Replacement Analysis and Summary

Vehicle #: 7702

Division/Unit: Fire Department

Year: 2007

Make/Model: Chevy Impala

Mileage: 60,165

FACTOR VALUE DESCRIPTION

Age 17 Age of vehicle.

Miles 60,165 Number of miles.

Type of Service Light-Duty Type of service that vehicle receives. For instance, a

police patrol car would be given "Severe" because it is in severe duty service. In contrast, an administrative sedan would be given "Admin," while light duty trucks

will be given "Light-Duty."

Condition Fair Takes into consideration body condition, rust, interior

condition, history, anticipated repairs, etc. Categories include, New, Very Good, Good, Fair, and Poor.

SUMMARY*

Fleet Manager's Due to the age of Recommendation: this asset is prone

Due to the age of the vehicle and operating conditions, this asset is prone to several failures. One of these failures comes in the form of fluid leaks. At 17 years this unit has high engine idle hours which make it susceptible to needing engine and transmission repairs which can and will be expensive in the foreseeable future. Also, due to the age of the vehicle parts may be discontinued or backorder which can

parts may be discontinued or backorder which can delay the vehicle from returning to the road. To sum up everything that has been stated, this unit qualifies

for replacement.

City of Pembroke Pines Fleet Services Vehicle Replacement Analysis and Summary

Vehicle #: 7703

Division/Unit: Fire Department

Year: 2007

Make/Model: Chevrolet Impala

Mileage: 62,178

FACTOR VALUE DESCRIPTION

Age 17 Age of vehicle.

Miles 62,178 Number of miles.

Type of Service Light-Duty Type of service that vehicle receives. For instance, a

police patrol car would be given "Severe" because it is in severe duty service. In contrast, an administrative sedan would be given "Admin," while light duty trucks

will be given "Light-Duty."

Condition Fair Takes into consideration body condition, rust, interior

condition, history, anticipated repairs, etc. Categories include, New, Very Good, Good, Fair, and Poor.

SUMMARY*

Fleet Manager's Due to the age of the vehicle and operating conditions, Recommendation: this asset is prone to several failures. One of these

failures comes in the form of fluid leaks. At 17 years this unit has high engine idle hours which make it susceptible to needing engine and transmission repairs which can and will be expensive in the foreseeable future. Also, due to the age of the vehicle parts may be discontinued or backorder which can delay the vehicle from returning to the road. To sum

delay the vehicle from returning to the road. To sum up everything that has been stated, this unit qualifies

for replacement.

| | Vehicles Sent or Marked for Surplus | | | | | |
|-----------|-------------------------------------|------------------|--------------------|--|--|--|
| Vehicle # | Department | Description | Status | | | |
| 2235 | TECHNOLOGY DEPARTMENT | 2016 GMC TERRAIN | 8 YEAR OLD GMC SUV | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | <u> </u> | 1 | | | | |

City of Pembroke Pines Fleet Services Vehicle Replacement Analysis and Summary

Vehicle #: 2235

Division/Unit: Technology

Department

Year: 2016

Make/Model: GMC Terrain

Mileage: 60,165

FACTOR VALUE DESCRIPTION

Age 8 Age of vehicle.

Miles 60,165 Number of miles.

Type of Service Light-Duty Type of service that vehicle receives. For instance, a

police patrol car would be given "Severe" because it is in severe duty service. In contrast, an administrative sedan would be given "Admin," while light duty trucks

will be given "Light-Duty."

Condition Fair Takes into consideration body condition, rust, interior

condition, history, anticipated repairs, etc. Categories include, New, Very Good, Good, Fair, and Poor.

SUMMARY*

Fleet Manager's Recommendation:

Due to the age of the vehicle and operating conditions, this asset is prone to several failures. One of these failures comes in the form of fluid leaks. At 8 years this unit has high engine idle hours which make it susceptible to transmission repairs which can and will be expensive in the foreseeable future. Also, due to the age of the vehicle parts may be discontinued or backorder which can delay the vehicle from returning to the road. To sum up everything that has been stated, this unit qualifies for replacement.